

1/15

Figure 1






Figure 2




2/15

Figure 3A




3/15

Figure 3B




4/15


Figure 4




5/15

Figure 5



6/15

Figure 6 (Lower resolution FE-SEM image)**Figure 7** (Lower resolution FE-SEM image)

7/15


Figure 8 (Lower resolution FE-SEM image)**Figure 9** (Higher resolution FE-SEM image)

8/15

Figure 10 (Higher resolution Fe-SEM image)**Figure 11** (Higher resolution Fe-SEM image)


9/15

Figure 12 TEM image




10/15

Figure 13 TEM image




11/15

Figure 14A,B CNT observed in reactor on metal particle splashes on collecting surface.




12/15

Figure 14C




13/15

Figure 15



14/15

Figure 16



15/15

Figure 17

